
Schraube am Motor montiert

BOLT IS REMOVED FROM CORNER OF ENGINE HSG THEN REINSTALLED WITH THE CABLE GUIDE IN PLACE.



E4-01383A-01