



YM 8021 SPK	12A-377D843
GES 53	12A-378R878
GES 53 H	12A-378Q878
CPG 53 BM	12A-378R841
CPG 53 HM	12A-378S841
530 HM	12A-378S889
HB 53 RLSK	12A-377D890
HB 53 RB	12A-378E890
53 HA	12A-378Q821, 12A-378Q821
478 SP	12A-378R811
RB 53-5R	12A-378R828
HB53RT	12A-373N890
53SP	12A-378R822
GES53H	12B-378S878
GES53H	12A-378Q802







- 27 Honda-Motor
CPG53-H, 530-HM
GES53H, 12B-378S878
- 27A Honda-Motor
GES53H, 12A-378Q878 / 53HA, 12A-378Q821
- 27B Honda-Motor
GES53H, 12A-378Q802
- 27C Honda-Motor
53HA, 12A-378Q821



- 30 YM8021 SPK, HB53 RLSK
KAWA-Motor
- 31 HB53RT
TEC-Motor

nicht abgebildet
not shown



E3-02540A-01